



CENTER SECTION




17. Mounting Bulkhead



CONNECTOR SECTION



WINGS




Note: You may wish to drill a 3mm hole in this approximate location in 2 of this piece in order to light the antenna base on top.

STERN ARMATURE PART ID

WINGS



CENTER SECTION



CONNECTOR SECTION

